



WEAVER CONSTRUCTION MANAGEMENT, INC.
 3679 S. Huron St., Suite 404
 Englewood, CO 80110
 Phone: (303) 789-4111 FAX: (303) 789-4310

SUBMITTAL TRANSMITTAL

December 7, 2011
Submittal No: 13100-001.A

PROJECT: Harold Thompson Regional WRF
 Birdsall Rd.
 Fountain, CO 80817
 Job No. 2908

ENGINEER: GMS, Inc.
 611 No. Weber St., #300
 Colorado Springs, CO 80903
 719-475-2935 Roger Sams

OWNER: Lower Fountain Metropolitan
 Sewage Disposal District
 901 S. Santa Fe Ave.
 Fountain, CO 80817
 719-382-5303 James Heckman

CONTRACTOR: McDade Woodcock, Inc.
 7222 Commerce Center Drive, #245
 Colorado Springs, CO 80909
 719-264-1236

SUBJECT: Resubmittal - Response letter to the Lightning Protection review on 11/30/11

SPEC SECTION: 13100

PREVIOUS SUBMISSION DATES:

DEVIATIONS FROM SPEC: ___ YES X NO

CONTRACTOR'S STAMP: This submittal has been reviewed by Weaver General Construction and approved with respect to the means, methods, techniques, & safety precautions & programs incidental thereto. Weaver General Construction also warrants that this submittal complies with contracted documents and comprises on deviations thereto:

Contractor's Stamp:

Engineer's Stamp:

Date: 12/17/11
 Reviewed by: H.C. Myers
 (X) Reviewed Without Comments
 () Reviewed With Comments

ENGINEER'S
 COMMENTS:

—



3788 INTERPARK DRIVE
COLORADO SPRINGS, CO 80907
(719) 488-2315 • (303) 762-0282
FAX: (719) 488-3612
WWW.MRLIGHTNING.COM
EMAIL: INFO@MRLIGHTNING.COM

December 2, 2011

McDade Woodcock, Inc.
7222 Commerce Center Drive, #245
Colorado Springs, CO 80919
Attn: Patrick Danenberg

Re: Harold D. Thompson WRF
Fountain, Colorado
Submittal review dated 11/30/11

Patrick,
Following are our responses to the Engineer's comments regarding our Submittals:

Item:

1. LP System Components
 - a. No exceptions taken to the LP system components provided components selected for each facility comply with NFPA 780 and UL 96A requirements, and materials selected are appropriate for building materials at each building.

Acknowledged

2. Headworks Building Layout
 - a. The entire building interior is a hazardous area (Class I, Div. 2), except the electrical room. Revise proposed installation drawing to indicate compliance with requirements for hazardous locations. Installation shall either utilize wiring methods and components of a type suitable for the hazardous location per NEC Chapter 5, or shall avoid interior space by keeping lightning protection conductors and components on the exterior surface of the building.

Acknowledged

 - b. Steel panels are proposed for both the roof and the wall coverings for the building. Any exposed LP system materials shall be suitable.

Acknowledged

 - c. The submittal states the LP system must be bonded to water system, fire suppression and electrical ground systems. The building does not have fire suppression. Do not connect lightning protection system directly to water piping.

Acknowledged

STANDARD OF EXCELLENCE





3788 INTERPARK DRIVE
COLORADO SPRINGS, CO 80907
(719) 488-2315 • (303) 762-0282
FAX: (719) 488-3612
WWW.MRLIGHTNING.COM
EMAIL: INFO@MRLIGHTNING.COM

3. Per the Owner's direction, the Underwriters Laboratories (UL) certification is not a requirement; however, materials and workmanship must be in accordance with UL requirements.

Acknowledged

Please feel free to contact me if you have questions.

Allen Scott Corey
President

STANDARD OF EXCELLENCE

